



Cambelt replacement. From £185



If there's one thing you really don't want to happen...

We don't like being alarmist, but cambelt failure is pretty serious stuff. If yours goes, it can mean the end of the road for your engine. And, if they're not changed at the recommended intervals, they do go. Over time and miles, the rubber deteriorates; it's not just through wear, but rain, salt, heat, ice, grit, you name it... eat away at the rubber and it can suddenly snap. We recommend you replace your cambelt at least every four years and sooner if your mileage is high.

Cambelt replacement

- Carried out by Volkswagen-trained technicians
- Using specialist tools and technology
- Only Volkswagen Original Parts® fitted (covered by 2-year parts and labour warranty*)
- Courtesy vehicles available
- Collect and return service available



A competitive price. Promise.

We'll match any like-for-like written quote using Volkswagen Original Parts® from any garage within 5 miles. It's that simple.

Keith Garages Ltd.

Bicester Road, Aylesbury, Buckinghamshire HP19 8AL

01296 317 000

Opening hours:

7.30am to 8.00pm Monday to Saturday

*2 year warranty excludes wear and tear, please ask a Service Advisor for full details.